## When different LED bar connector, direct soldering working guide.

1.) When different LED Bar connector 3-1. Tester use pattern check(Not open)






4-1. If not open case, could you soldering.



2.) Cutting the in cable for connector.



3-2. Tester use pattern check(open)



4-2. If not open case, could you soldering.

