

Tabela nastavaka

Tip nastavka	Specifikacije
Phillips (PH)	PH0000, PH000, PH00, PH0, PH1, PH2
Umetnuti Phillips	IN PH2
Ravni (Slotted, SL)	SL 1.0, SL 1.3, SL 1.5, SL 2.0, SL 2.5, SL 3.0, SL 3.5, SL 4.0
Torx (T)	T 1, T 2, T 3, T 4, T 5, T 6, T 7, T 8, T 9, T 10, T 15, T 20
Torx-sigurnosni (Torx Security, "H")	T 5H, T 6H, T 7H, T 8H, T 9H, T 10H, T 15H, T 20H, T 25H
Pentalobe (P)	P 2, P 5, P 6, P 8
Pozidriv (PZ)	PZ 000, PZ 00, PZ 0, PZ 1, PZ 2
Allen / Inbus metrički (H)	H 0.7, H 0.9, H 1.3, H 1.5, H 2.0, H 2.5, H 3.0, H 3.5, H 4.0, H 4.5, H 5, H 6
Allen imperijalni (hex imperial)	H 1/16, H 1/8, H 3/32, H 5/32, H 5/64, H 7/64, H 9/64
Tri-wing (Y)	Y 0.6, Y 1.0, Y 1.5, Y 2.0, Y 2.5, Y 3.0, Y 3.5
Trokutni (Δ)	Δ 2.0, Δ 2.3, Δ 2.6, Δ 3.0
Clutch-bitovi (U)	U 1.7, U 2.0, U 2.6, U 3.0, U 8
Kvadrat (Square, S)	S 0, S 1, S 2
Spline (W)	W 1.5, W 2.0, W 2.5
Penta-/bezalja	0.8, 1.0
Navojni nastavci "#" (nut-driver)	2.5#, 3.0#, 3.5#, 4.0#, 4.5#, 5.0#, 5.5#, 6.0#, 7.0#
Navojni metrički (M)	M 2.5, M 3.0, M 3.5, M 4.0, M 4.5, M 5.0, M 5.5
Navojni imperijalni (G)	G 3.8, G 4.5

Magnetni pickup-bit

U

Vanjski Torx (External Torx, Ex)

Ex 6, Ex 7, Ex 8, Ex 9, Ex 10

Svrdla (Drill bits, Dr)

Dr 6, Dr 7, Dr 8, Dr 9, Dr 10