

Pro'sKit®

Professional Tool Solutions Since 1991

3 5/6 TRUE RMS MULTIMETER

CAT II 600V



**TRUE RMS
AUTO RANGE
OVERLOAD PROTECTION**

**NCV Detection
LED Light**

MT-1236



LED Light

NCV Detect

LCD Screen

NCV
Indication

Data Hold


Test Lead
Socket

Function
Selection
Buzzer

Backlight

Rotary
Switch











NCV Double Indication

Buzzer & LED Indication
For NCV Detection









DCV Measurement



ACV Measurement



Resistance Test



Diode Test



Capacitance Test



DCA Measurement



Continuity Test



Temperature Test

